

OFFICE ENGINEER NPP SIYANA DISTRICT BULANDSHAHR

S.NO.


DATE 9-3-2022

BUILDING SAFETY CERTIFICATE

It is certified that the building of CHANDRAWATI PUBLIC SCHOOL SIYANA is in good condition to run a school. Inspection is done by engineer of nagar palika parishad siyana distt. Bulandshahr and made the report that school is safe to run school.

Therefore NPP siyana is issuing building safety certificate to chandrawati public school siyana for the next five years.

Office Engineer:


अधिसासी अधिकारी
नगर पालिका परिषद
सियाना (बुलंदशहर)

Nagar palika parishad
Siyana (Bulandshahr)