

SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No. _____

Date:06/01/2022

It is certified that an inspection team headed by Mr. LATESH KUMAR
(Name of officers with designation)

From Nagar Palika Parishad ,Siyana BSR inspected
the Chandrawati Public School, Bugrasi Road Siyana (Bulandshahr)
on 06/01/2022 and

found that the Chandrawati Public School has safe drinking water facilities for
the students and members of staff of the institute and is maintaining the hygienic
sanitation

condition in the school building & the campus as per the norms prescribed by
the central/state/U.T Govt.

The above valid for a period of 06/01/2022 - 06/01/2023

Signature with seal
नगरपालिका अधिकारी
नगरपालिका परिषद
सियाणा (बुलंदशहर)

Name: लतेश कुमार

Destination:

प्रधान लिपिक

To
Chandrawati Public School
Bugrasi Road ,Siyana
Bulandshahr(U.P)
(Name & address of the institute)